

FIG.1A




FIG.1B




FIG.1C

HAZE DEGREE OF GLOSS HAZE




FIG.1D




FIG.2




FIG.4A





FIG.4B






FIG.5B

1PASS

A large, hollow arrow pointing horizontally to the right, indicating a transition from the state in FIG. 5A to FIG. 5B.




FIG.5A

2PASS

A large, hollow arrow pointing horizontally to the right, indicating a transition from the state in FIG. 5A to FIG. 5C.




FIG.5C

4PASS

A large, hollow arrow pointing horizontally to the right, indicating a transition from the state in FIG. 5A to FIG. 5D.




FIG.5D

6/20




FIG.6A




FIG.6B




FIG.6C

7/20




FIG.7





FIG.8

FIG.9A


1ST PASS



0 %

FIG.9B


2ND PASS



80 %

FIG.9C


2ND PASS



70 %

FIG.9D

2ND PASS



60 %

10/20





FIG.10

11/20


SAME MASK FOR EJECTION OPENING ROWS A AND B

FIG.11A



MASK INVERTED BETWEEN OPENING EJECTION ROWS A AND B


FIG.11B



HEAD SCAN DIRECTION



FIG.11C



12/20





FIG.12






FIG.14

FIG.15A




FIG.15B




FIG.15C




FIG.16A





FIG.16B






FIG.17

20		1	2	1	
		2	1	2	
		1	2	1	

FIG.18

FIG.19A




FIG.19B





FIG.19C






FIG.20